

# Water Testing Results - Mapleton School District

## Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
MS Room 1-Sink	20850300-001CF	6/15/2022	21.5
MS Room 5-Sink	20850300-002CF	6/15/2022	2.7
MS Room 9-Sink	20850300-003CF	6/15/2022	46.8
MS Room 10-Sink	20850300-004CF	6/15/2022	ND
MS Main Restroom-Bathroom Faucet	20850300-005BF	6/15/2022	2710
MS Staff Restroom-Bathroom Faucet	20850300-006BF	6/15/2022	2.27
HS Boys Locker Room-Bathroom Faucet	20850200-010BF	6/15/2022	ND
HS Girls Locker Room-Bathroom Faucet	20850200-011BF	6/15/2022	ND
HS Commons-Sink	20850200-012CF	6/15/2022	ND
HS Courtyard-Drinking Fountain	20850200-013DW	6/15/2022	17.4
HS UH Girls Left-Bathroom Faucet	20850200-014BF	6/15/2022	ND
HS UH Girls Mid-Bathroom Faucet	20850200-015BF	6/15/2022	ND
HS UH Girls Right-Bathroom Faucet	20850200-016BF	6/15/2022	ND
HS UH Boys Left-Bathroom Faucet	20850200-017BF	6/15/2022	ND
HS UH Boys Mid-Bathroom Faucet	20850200-018BF	6/15/2022	ND
HS UH Boys Right-Bathroom Faucet	20850200-019BF	6/15/2022	ND
HS UH Drink Fount L-Drinking Fountain	20850200-020DW	6/15/2022	ND
HS UH Drink Fount R-Drinking Fountain	20850200-021DW	6/15/2022	ND
HS UH Drink Fount W-Bottle Filler	20850200-022WB	6/15/2022	ND
HS UH Staff Rest-Bathroom Faucet	20850200-023BF	6/15/2022	ND
HS UH Kitchen Area-Kitchen Faucet	20850200-024KF	6/15/2022	ND
HS UH Kitchen Handwash-Kitchen Faucet	20850200-025KF	6/15/2022	2.59
HS LH Staff BreakRoom-Sink	20850200-026CF	6/15/2022	ND
HS LH Staff Restroom-Bathroom Faucet	20850200-027BF	6/15/2022	ND
HS Room 1 Left-Sink	20850200-028CF	6/15/2022	ND
HS Room 1 Center-Sink	20850200-029CF	6/15/2022	ND
HS Room 1 Right-Sink	20850200-030CF	6/15/2022	ND
HS LH Boys Left-Bathroom Faucet	20850200-031BF	6/15/2022	ND

HS LH Boys Mid-Bathroom Faucet	20850200-032BF	6/15/2022	2.4
HS LH Boys Right-Bathroom Faucet	20850200-033BF	6/15/2022	ND
HS LH Girls Left-Bathroom Faucet	20850200-034BF	6/15/2022	4.32
HS LH Girls Mid-Bathroom Faucet	20850200-035BF	6/15/2022	ND
HS LH Girls Right-Bathroom Faucet	20850200-036BF	6/15/2022	ND
HS Room 3 Left-Sink	20850200-037CF	6/15/2022	3.99
HS Room 3 Mid-Sink	20850200-038CF	6/15/2022	6.21
HS Room 3 Right-Sink	20850200-039CF	6/15/2022	<b>16.6</b>
HS LH Drink Fount L-Drinking Fountain	20850200-040DW	6/15/2022	ND
HS LH Drink Fount R-Drinking Fountain	20850200-041DW	6/15/2022	ND
HS LH Drink Fount W-Bottle Filler	20850200-042WB	6/15/2022	ND
ES Room 1-Drinking Fountain	20850100-050DW	6/15/2022	ND
ES Room 1-Sink	20850100-051CF	6/15/2022	ND
ES Room 1-Bathroom Faucet	20850100-052BF	6/15/2022	ND
ES Room 2-Drinking Fountain	20850100-053DW	6/15/2022	ND
ES Room 2-Sink	20850100-054CF	6/15/2022	ND
ES Room 2-Bathroom Faucet	20850100-055BF	6/15/2022	ND
ES Room 3-Drinking Fountain	20850100-056DW	6/15/2022	ND
ES Room 3-Sink	20850100-057CF	6/15/2022	ND
ES Room 3-Bathroom Faucet	20850100-058BF	6/15/2022	ND
ES Room 4-Drinking Fountain	20850100-059DW	6/15/2022	ND
ES Room 4-Sink	20850100-060CF	6/15/2022	2.34
ES Room 4-Bathroom Faucet	20850100-061BF	6/15/2022	ND
ES Room 5-Drinking Fountain	20850100-062DW	6/15/2022	ND
ES Room 5-Sink	20850100-063CF	6/15/2022	ND
ES Room 5-Bathroom Faucet	20850100-064BF	6/15/2022	4.88
ES Room 6-Drinking Fountain	20850100-065DW	6/15/2022	3.55
ES Room 6-Sink	20850100-066CF	6/15/2022	ND
ES Room 6-Bathroom Faucet	20850100-067BF	6/15/2022	2.91
ES Room 7-Drinking Fountain	20850100-068DW	6/15/2022	ND
ES Room 7-Sink	20850100-069CF	6/15/2022	2.06
ES Room 7-Bathroom Faucet	20850100-070BF	6/15/2022	2.14
ES Room 8-Drinking Fountain	20850100-071DW	6/15/2022	ND
ES Room 8-Sink	20850100-072CF	7/6/2022	<b>14.5</b>

ES Room 8-Bathroom Faucet	20850100-073BF	7/6/2022	5.47
ES Room 9-Sink	20850100-074CF	6/15/2022	4.41
ES Room 9-10 Rest-Bathroom Faucet	20850100-075BF	6/15/2022	ND
ES Room 10-Sink	20850100-076CF	6/15/2022	2.54
ES Room 11-12 Rest-Bathroom Faucet	20850100-077BF	6/15/2022	ND
ES ES Office Main-Staff Sink	20850100-078SF	6/15/2022	ND
ES ES Office Back-Staff Sink	20850100-079SF	6/15/2022	3.58
ES ES Rest Front-Bathroom Faucet	20850100-080BF	6/15/2022	2.15
ES ES Rest Mid-Bathroom Faucet	20850100-081BF	6/15/2022	ND
ES ES Rest Back-Bathroom Faucet	20850100-082BF	6/15/2022	ND
ES Kitchen Dish Sink-Kitchen Faucet	20850100-083KF	6/15/2022	5.16
ES Kit Rear Sink L-Kitchen Faucet	20850100-084KF	6/15/2022	ND
ES Kit Rear Sink R-Kitchen Faucet	20850100-085KF	6/15/2022	8.16
ES Kitchen Office-Sink	20850100-086CF	6/15/2022	106
ES Kitchen Rest-Bathroom Faucet	20850100-087BF	6/15/2022	ND
ES MPR Drink L-Drinking Fountain	20850100-088DW	6/15/2022	ND
ES MPR Drink R-Drinking Fountain	20850100-089DW	6/15/2022	ND
ES MPR Drink W-Bottle Filler	20850100-090WB	6/15/2022	ND
ES MPR Rest L-Bathroom Faucet	20850100-091BF	6/15/2022	ND
ES MPR Rest R-Bathroom Faucet	20850100-092BF	6/15/2022	ND
Trans Restroom-Bathroom Faucet	20850002-100BF	6/15/2022	ND
Indust Restroom-Bathroom Faucet	20850001-110BF	6/15/2022	9.87
Indust Left Art Sink-Sink	20850001-111CF	6/15/2022	6.84
Indust Middle Art Sink-Sink	20850001-112CF	6/15/2022	3.13
Indust Right Art Sink-Sink	20850001-113CF	6/15/2022	3.29
Conces Concessions-Kitchen Faucet	20850003-120KF	6/15/2022	97.2
Conces Field North Fount-Drinking Fountain	20850003-121DW	6/15/2022	ND
Conces Field South Fount-Drinking Fountain	20850003-122DW	6/15/2022	21.2
Conces Field Track Fount-Drinking Fountain	20850003-123DW	6/15/2022	15
ES Room 9 Drink-Drinking Fountain	20850100-093DW	6/15/2022	5.3
ES Room 10 Drink-Drinking Fountain	20850100-094DW	6/15/2022	4.42

<b>Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing</b>			
<b>RETESTS</b>			
ND = Non Detect - Lead level is below the set detection limits			of 2 ppb